There is a settlement with Interline Brands Inc. ("Interline") about DuraProTM toilet connectors with certain types of plastic coupling nuts that could fail and cause water damage. Interline denies that it has done anything wrong.

The settlement covers the purchase and possession of a DuraProTM toilet connector with certain types of plastic coupling nuts and payments for replacement toilet connectors or repairs for property damage caused by the failure of the plastic coupling nuts.

Who's Included? The settlement includes anyone who owns or owned, or leases or leased, a residence or other structure located in the United States containing a DuraProTM toilet connector with plastic coupling nuts with either a six-ribbed design or bi-wing design, or who otherwise suffer or have suffered property damage from the failure of these plastic coupling nuts on the toilet connector. Images of included toilet connectors are available at www.DuraProToiletConnectorSettlement.com.

What does the Settlement provide? The settlement agreement provides for the payment of \$16.5 million into a settlement fund to: (1) pay Class Members for replacement of DuraProTM toilet connectors and/or property damage due to failure of the coupling nuts; (2) cover notice and settlement administration expenses; (3) pay attorneys' fees as ordered by the Court of up to one-third of the settlement fund (or \$5.5 million), plus up to \$500,000 in expenses; and (4) pay a total incentive award of up to \$25,000 to the five Class Representatives (\$5,000 each).

What can your customers get? Class Members filing a claim for replacement of toilet connectors can get up to \$20 (maximum of five at \$4 per replacement). Class Members filing a claim for property damages can recover up to 30% of their documented repair costs and related damages.

Please tell your customers about this Settlement

For more information or a Claim Form:

U8491 v.02

Ajose v. Interline Claims Administrator PO Box 2876 Portland, OR 97208-2876

DURAPROTM Toilet Connector Settlement

Please Share this Notice with Your Customers